

FIG. 1




FIG. 2




FIG. 3




FIG. 4



30




FIG. 5





FIG. 6



OBLON ET AL (703) 413-3000
DOCKET # 0039-7444-0TTC
INV. Masahiro SAITOU et al.
USSN 09/448,144
Reply to N.O.A. DATED July 26, 2005
REPLACEMENT DRAWINGS



————— GENERATED VOLTAGE
----- CONTACT RESISTANCE

FIG. 7




FIG. 8



OBLON ET AL (703) 413-3000
DOCKET # 0039-7444-0TTC
INV. Masahiro SAITOU et al.
USSN 09/448,144
Reply to N.O.A. DATED July 26, 2005
REPLACEMENT DRAWINGS




FIG. 9 (PRIOR ART)




FIG. 10 (PRIOR ART)



OBLON ET AL (703) 413-3000
DOCKET # 0039-7444-0TTC
INV. Masahiro SAITOU et al.
USSN 09/448,144
Reply to N.O.A. DATED July 26, 2005
REPLACEMENT DRAWINGS




FIG. 11(PRIOR ART)



OBLON ET AL (703) 413-3000
DOCKET # 0039-7444-0TTC
INV. Masahiro SAITOU et al.
USSN 09/448,144
Reply to N.O.A. DATED July 26, 2005
REPLACEMENT DRAWINGS




FIG. 12 (PRIOR ART)